Mosta 18w Compatible Dimmers

	Quantity	Result	Observation	Acoustics	Comments
	Varilight V-Pro JQP401	V	100-5% Smooth Dim	Faint Buzzing from driver	Recommended
	Varilight P251	×	100-10% Smooth Dim	Constant Buzzing from driver and dimmer	Not Recommended
	Varilight MJP120	~	90%-Off Smooth Dim	Faint Buzzing from driver and dimmer	Conditional – Faint buzzing from both driver and dimmer
	Varilight V-Com MKP180	×	100-5% Smooth Dim	Constant Buzzing from Driver and Dimmer	Not Recommended
	ZANO ZGRID500	×	100-10% Smooth Dim	Constant Buzzing from Driver and Dimmer	Not Recommended
mer	ZGRIDLED 250	\checkmark	100-Off Smooth Dim	Noise Free	Recommended
Dimm	Newlec NLSL8306/12	×	100-1% Smooth Dim	Faint Buzzing from driver	Recommended
	Newlec NL8815W	~	100-25% Smooth Dim	Faint Buzzing from Driver	Conditional – limited dimming range and buzzing from driver
	Newlec NL8806W	\checkmark	100-10% Smooth Dim	Noise Free	Recommended
	Hamilton 7WC1X100	V	100-5% Incremental Dim	Faint Buzzing from Driver	Conditional - dims in steps
	Hamilton LED ITB100	V	100-5% Smooth Dim	Faint Buzzing from Driver	Recommended
	Hamilton Litestat 40-400W	×	100-10% Responsive Dim	Constant Buzzing from Driver and Dimmer	Not recommended
	Hamilton Litestat 25-250W	\checkmark	100-5% Smooth Dim	Noise Free	Recommended

Please Note: KSR test these dimmers singularly please consult the dimmer manufacturer for recommendations on other scenarios. All recommendations are correct as per the date tested below. KSR cannot be held responsible for any changes in the dimmer specification.